

# PRESIDENT JFK

## VCO ALIGNMENT =====

### 1. Test Equipment Required

- a) Oscilloscope (100 MHz).
- b) DC Power Supply (13.8v, 3 Amps).
- c) DC Voltmeter (DVM).
- d) Frequency Counter (100 MHz).

### 2. Alignment Procedure

STEP	PRESET TO	ADJUSTMENT	REMARKS
1	Channel :1 Band : MID Mode : RX	L17	Connect DC Voltmeter to TP1 (Lead of R72). Adjust L17 for 1.2 Volts $\pm$ 0.1 Volt on Voltmeter.

### 3. Test Equipment Connection

